



LEGEND
Street furniture & Services

Over Head Wires (LUAS) - Python ESB	Bus Stop	Ballast	Beacon	Coalhole Cover	Electricity Pole	Telegraph pole	OCIS Pole	OCIS Camera Pole	Lamp Post	Four Manhole	Surface Water MH	Manholes	Air Conditioning Vents	Services Inspection Cover	Traffic Inspection Cover	Cable TV Inspection Cover	ESAT Inspection Cover	NL Inspection Cover	Encom Inspection Cover	Rolling Eye	Water Level	Water Level	Water Level	Fair Way	Fair Way	Fair Way	Green	Green	Green	Tea Box	Other	Survey Station	Photo point
Phone Box	Bus Shelter	Ballast	Beacon	Coalhole Cover	Electricity Pole	Telegraph pole	OCIS Pole	OCIS Camera Pole	Lamp Post	Four Manhole	Surface Water MH	Manholes	Air Conditioning Vents	Services Inspection Cover	Traffic Inspection Cover	Cable TV Inspection Cover	ESAT Inspection Cover	NL Inspection Cover	Encom Inspection Cover	Rolling Eye	Water Level	Water Level	Water Level	Fair Way	Fair Way	Fair Way	Green	Green	Green	Tea Box	Other	Survey Station	Photo point

Natural Features

Built Features

Roads & Road Markings

Other

Murphy Surveys Ltd. Disclaimer

The user or recipient of this survey data understands and acknowledges this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Wherever possible, areas unable to be surveyed will be labelled as 'UTS'.

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or damages suffered by the Client.

The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such imprecision or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified scale or accuracy.

Site Location

North

Map Sheet Layout

Map Sheet 0000

Drawn by: KM MA	Date: 08.08.2022	Datum: Main Head
Checked by: SQ	Date: 08.09.2022	Grid System: Irish National Grid
Checked by: RV	Date: 21.09.2022	Irish National Grid

No	Date	Description
0	21.09.2022	First Drawing
1	06.02.2023	Additional Survey
2	09.03.2023	Balls repositioned and platform edge added

SCSI

RICS

THE SURVEY ASSOCIATION

EUROPEAN GPR ASSOCIATION

Murphy
GEOSPATIAL

Topographic surveys, Measured Building Surveys, Setting-Out, As-Built Surveys, Hydrographic Surveys, Light Mapping, Pipeline Surveys, Service Location, Ground Penetrating Radar, Laser Scanning, Rectified Photography

Kildare Cork Dublin Belfast Glasgow Manchester London Chennai

Head Office
Global House
Kilcullen Business Campus
Kilcullen Co. Kildare, Ireland

Phone: (+353) 045 484040
Fax: (+353) 045 484004
Email: info@murphyge.ie

Client: Ianrod Eireann

Project: RFQ_19160 Topo Oranmore Station

Date: 21.09.2022 **Scale:** NTS@A1

Description: Topographical Survey

Drawing Number: MGS47168_T_ITM_Rev2-00

© Copyright 2022 MURPHY GEOSPATIAL LTD

